ASS'T MOMENCLATURE: SHIRADER

SYSTEM: <u>NECHANICAL ARM SUBSYSTEM</u> ASS'Y P/N: STY40J1219

REF.	REV.	DRAWING REF. DESIGNATION	FATEURE MODE AMD CARISE	FIND ITEM	INDUM / TUNC; 3/1RAD RATIONALE FOR ACCEPTANCE CRETICALITY
4640		BHOULDER FUSING. 45 PRING CHANNEL FUSES. 16 BACK-UP CHANNEL FUSES. WIRENG SCHEMATEC 511406316 REVISION C.	MODE: LOSS OF PRIMARY OR BACK UP MEATER FUSE.  CAUSE(E): (1) MECHANICAL SHOCK VIDNATION, MATERIALB 4PRIME FUSES 24 TURGUGN 37 USUS 25 TURGUGN 14 AND 16)	ONE OF TWO 28Y HEATER WIRES TO A HEATER CROUP VILL SE LOST. HO EFFECT WILL BE HOTICED.  WORST CASE HO EFFECT ON CREWYVENICLE OR HISSION. REDANDANT PAINS REMANDANT PAINS REMAN	PUSES USED IN THE SHOULDER FUSE PLUG ASSEMBLIES ARE OF THE DESIGN OFFISED BY MSFC SPECIFICATION AGAINSTS. THE SHOW APPLICATION, DESIGN AND PROCESS IMPROVEMENTS MAVE BEEN MEGITATED WITH, AND THPLEMENTED BY, THE MANUFACTURER.  INFROMED ATTACHMENT OF END CAPS.  CONTROL OF FUSE ELEMENT LENGTH AND DISPOSITION WITHIN THE FUSE BODY TUBE.  CONTROL SOLDERING BELWEN FUSE ELEMENT AND THE END CAPS.  PRIOR TO ASSEMBLY IN THE FUSE PLUG ASSEMBLY, A CONNECT PIN IS SOLDERED TO EACH OF THE FUSE PLUG ASSEMBLY, IN COUNTROLLED BY ESTABLISHED PROCEDURES WHICH INCLUDE THE REQUIRERENT OF A "METEROP" QUALITY OF SOLDER FOR EACH SOLDER JOINT. THE FUSE BODY AND LEAD WIRES ARE SLEEVED TO PRICLUDE SHORT CHECKING. FACE FUSE AND ALL SOLDERED JOINT SARE SUBJECTED TO RADIOGRAPHIC INSPECTION.  THE FUSE PLUG ASSEMBLY INCLUDES AN ALLUMINANT FUSES. THE CONNECTOR ASSEMBLY IS POTTED USING A SENI-RESILIED! (BTY) COMPOUND. THE POTTENG MEDIUM PROVIDES GOOD HEAT TRANSFER AND ENSURES MECHANICAL STABILITY OF THE INDIVIDUAL FUSES.  POMER TO THE END EFFECTOR MEATERS IS COMPUCIED BY 2 PARALLEL WIRES, EACH OF WHICH IS PROTECTED BY A 5 AMP FUSE.

EPARED BY: MING	SUPERCEDING DATE: 28 OCT 86	APPROVED BY:	DATE:
-----------------	-----------------------------	--------------	-------

## CRITICAL ITEMS LIST

SYSTEM: NECHANICAL ARM SUBSYSTEM
ASS'Y P/N: \$114011219 SHEET: 2

REF.	REV.	DRAWING RÉF. DESIGNATION	AND CAUSE	FATEURE EFFECT ON END ITEM	HOWN / FUNC. 3/TRAB RATIONALE FOR ACCEPTANCE CRITICALITY
4640		SHOULDER FUSING. 45 PRIME CHAMMEL FUSES. 16 BACK-UP CHAMMEL FUSES. WIRING SCHEMATIC STITOE316 REVISION C.	MODE: LOSS OF PRIMARY OR BACK UP HEATER FUSE.  CAUSE(S): (1) NECHAMICAL SHOCK VIORATION, MATERIALS (PRIME FUSES 24 IMMOUGH 37, B/U FUSES 2 THROUGH 14 AND 16)	ONE OF TWO 28Y HEATER WIRES TO A NEATER GROUP WILL BE LOST. HO EFFECT WILL BE NOTICED.  WORST CASE  NO EFFECT ON EREW/VENICLE OR MISSION.  REDURDANT PATHS REMAINING  1 FUSE FOR FAILED GROUP 2 FUSES FOR ALTERNATE SYSTEM HEATER GROUP	ACCEPTANCE TESTS  THE SHOULDER, ELBOM AND WRIST JOINTS ARE SUBJECTED TO THE FOLLOWING ACCEPTANCE ENVIRONMENTAL TESTING.  O VIBRATION: LEVEL AND DURATION - REFERENCE TABLES 9, 10 AND 11.  O THERNAL: *70 DEGREES C TO *25 DEGREES C (2 CYCLES) 1 K 10**6 TORK.  THE JOINTS ARE INTEGRATED UNTO THE RMS SYSTEM (PER 1P532) WHICH IS FURTHER TESTED IN (1P518 RMS STRONGBACK AND 1P552 FLAT FLOOR). THESE TESTS VERIFIES THE ABSENCE OF THE FAILURE MODE.  QUALIFICATION TESTS  THE SHOULDER AND MRIST JOINTS WERE SUBJECTED TO THE LISTED BELOW ENVIRONMENTS. THE ELBOW JOINTS WAS NOT EXPOSED THE GUALIFICATION ENVIRONMENTS WAS CERTIFIED BY SIMILARITY TO THE SHOULDER JOINT.  O VIBRATION: LEVEL AND DURATION REFERENCE TABLES 9 AND 10 SHOCK: 20G/11 MS *3 AXES (6 DIRECTIONS)  O THERMAL VACULUM: *81 DEGREES C TO *36 DEGREES C (6 CYCLES) 1 X 10**6 TORR.  O EMC: MIL-STD-461 AS MODIFIED BY SL-E-0002 (TESTS CEO1, CEO3, CSO1, CSO2, CSO6, REO2 (M/B).  O MUBHIDITY: ONLY SHOULDER JOINT MAS TESTED, 95% RH (55 DEGREES C MAINTAINED FOR 6 MS). (65 DEGREES C TO 30 DEGREES C MAINTAINED FOR 6 MS). (65 DEGREES C TABLE 12.  NOTE:  ELBOW JOINT (S/M 302 AND UP) INCORPORATES MON-WELDED TRANSITIONS WHICH WAS LOAD TESTED TO LOAD IN REFERENCE TABLE 18.  FLIGHT CHECKOUT
	I				RMS/MECH - 381

FREA RAVE BY B FAILURE MOVE FAILURE EFFECT HOWN / FUNC.  REF. REV. DRAWING REF. AND ON 3/1RAB RATI DESIGNATION CAUSE ENDITEN CRITICALITY	ONALE FOR ACCEPTANCE
BACK-UP CHAMMEL FUSES UNENDO SCHEMATIC \$11408316 REVISION C.  REVISION C.  REVISION REPROMPT AND 16)  REDAMDANT PATHS REMAINING RE	CIFICATION MIL-W-22759 OR MIL-W-81381 D TO MASA JSCHBOBO STANDARD MUMBER 95A.  MIFIES THAT ALL PARTS RECEIVED ARE AS REMENT DOCUMENTS, THAT MO PHYSICAL PARTS OURING SHIPMENT, THAT THE WIDE ADEQUATE TRACEABILITY INFORMATION ALY IDENTIFIES ACCEPTABLE PARTS.  PURICULT MANUFACTURE AND ASSEMBLY AS FACTURING STAGE COMPLETED. THESE  COTION FOR CORRECT SOLDERING, MIRE OPERATORS AND INSPECTORS ARE TRAINED IN 5300.4(3A) STANDARD, AS MODIFIED  REDERED CONTACTS OF THE FUSE ORADIOGRAPHIC INSPECTION TO CHECK IL FLAVS.  PECTIONS TO SPAR-ITP 257 VERIFY AT HIGH AND LOW TEMPERATURE (-38 ES C) (SPAR/GOVERNMENT REP.  MIF).  TED TO SPAR-ITP 257 WHICH AND THEMPAL CYCLING, MANDATORY INSPECTION POINT).  G WITH RECEPTICLE ON SHOULDER MS INCLUDE VISUAL, CLEANLINESS, IOM, CHECK FOR BENT OR PUSHED

REPARED BY: MFMG SUPERCEDING DATE: 28 OCT 86	APPROVED BY:	DATE:
--	--------------	-------

## CRITICAL ITEMS LIST

PROJECT: SAMS ASS'Y MOMENCLATURE: SHOULDER

SYSTEM: MECHANICAL ARM SUBSYSTEM
ASS'Y P/H: \$1140J1219 SHEET: 6

REF.	REV.	DRAWING REF. DESIGNATION	FATLURE MODE AND CAUSE	FATEURE EFFECT ON END ITEN	HOUR 7 FUNC. 3/1RAB RATIONALE FOR ACCEPTANCE CRITICALITY
4640	1	SHOULDER FUSING. 45 PRINE CHANNEL FUSES. 16 BACK-UP CHANNEL FUSES. WIRTING SCHEMATIC 51140E316 REVISION C.	MODE: LOSS OF PRIMARY OR BACK UP MEATER FUSE.  CAUSE(S): (1) MECHANICAL SHOCK VIBRA! ION, MATERIALS (PRIME FUSES 24 THROUGH 37, BATERIALS THROUGH 14, AND 16)	ONE OF TWO 28V HEATER WIRES TO A HEATER GROUP WILL BE LOST. NO EFFECT WILL BE NOTICED.  WORST CASE  NO EFFECT ON CREW/VEHICLE OR MISSION. REDUNDANT PATHS REMARKING  1 FUSE FOR FAILED GROUP 2 FUSES FOR ALTERNATE STSTEM MEATER GROUP	A TEST READINESS REVIEW (TRR) UNION INCLUDES VERIFICATION OF TEST PERSONNEL, TEST DOCUMENTS, TEST EQUIPMENT CALIBRATION/VALIDATION STATUS AND MARDMARE CONFIGURATION IS CONVENED BY QUALITY ASSURANCE IN COMMITTE MEDITER RING, RELEABILITY, CONFIGURATION CONTROL, SUPPLIER AS APPLICABLE, AND THE GOVERNMENT REPRESENTATIVE, PRIOR TO THE START OF ANY FORMAL TESTING (ACCEPTANCE OF QUALIFICATION).  JOINT LEVEL ACCEPTANCE TESTING (ATP) INCLUDES AMBINET, VIBRATION AND THERMAL-VAC TESTING.  (SPAN, GOVERNMENT REP MANDATORY INSPECTION POINT).  SAMS SYSTEMS INTEGRATION, THE INTEGRATION OF MECHANICAL ARM SUBASSEMBLIES AND THE FLIGHT CABIN EQUIPMENT TO FORM THE SAMS. INSPECTIONS ARE PERFORMED AT EACH PHASE OF INTEGRATION UNICH INCLUDES GROUNDING CHECKS, THRU WIRTING CHECKS, WIRING ROUTING, INTERFACE CONNECTORS FOR BEHT OR PUSH BACK CONTACTS ETC.  SRMS SYSTEMS TESTING - STRONGBACK AND FLAT FLOOR AMBIENT PERFORMANCE TEST. (SPAR/GOVERNMENT REP MANDATORY INSPECTION POINT)
					RMS/MECH - 383

ET:

REF. REV. DRAWING REF. AND DESIGNATION CAUSE	FATLURE EFFECT ON END TEN	HOUR / FUNC: 3/1RAB RATIONALE FOR ACCEPTANCE CRITICALITY
SHOULDER FUSING, 45 PRINE CHANNEL FUSES, 16 BACK-UP CHANNEL FUSES, WIRTING SCHEMATIC S1140E316 REVISION C. PRIME FUSE (PRIME FUSE 24 THROUGH 37, B/U FUSES 2 THROUGH 14 AND 16)	NO EFFECT ON CREW/VENICLE OR MISSION.	THE FOLLOWING FAILURE ANALYSIS REPORT(S) ARE RELEVANT:  FAR 2114: S/M 202 JUL 80  DESCRIPTION  HIGH RESISTANCE FOLLOWING THERNAL CYCLING CAUSED BY NFG. DEFECT.  CORRECTIVE ACTION  MFG TO IMPLEMENT THERNAL TESTING. (FMEA NO. 4590, 4670)  FAR 2120: S/M 201 JAN 81  DESCRIPTION  HIGH RESISTANCE, MFG DEFECT. REFER TO FAR 2114. OUT-PUT DID  MOT SWITCH, FOLLOWING MUNIDITY TEST, DUE TO SMORTED LED  CORRECTIVE ACTION  REFER TO FAR 2114 (FMEA NO.4590, 4670) REPLACED LED.  FAR 2358: S/M 302 MAY 83  DESCRIPTION  FUSE FAILED OPEN, CAUSED BY DAMAGED SOLDER CONN DURING REMORK.  CORRECTIVE ACTION  SCRAPPED REMORKED PUSES. ECH S1130 MODIFIED TESTING. (FMEA  NO. 4590, 4670)  FAR 2370: S/M 304 NOV 03  DESCRIPTION  VOLTACE DROP EXCESSIVE, CAUSE DESIGN/MANUFACTURING FAULT.  CORRECTIVE ACTION  SCRAPPED ALL FUSES, PREPARED NEW FUSE SPEC. (FMEA NO. 4590; 4670)

REPARED BY: HFMG SUPERCEDING DATE: 28 OCT 86	APPROVED BY:		DATE:
--	--------------	--	-------

## CRITICAL ITEMS LIST

THEX

PROJECT: SRMS ASS'Y NOMENCLATURE: SHOULDER

SYSTEM: MECHANICAL ARM SUBSYSTEM ASS'Y P/N: 51140J1219

SHEET: 6

DRAWING REF. TAILURE MODE TAILURE EFFECT HOUR 7 FURC. REF. MEV. AND 3/1RAB DESIGNATION RATIONALE FOR ACCEPTANCE CAUSE END ITEM CRITICALITY 4640 1 SHOULDER OHE OF THO 26V OPERATIONAL EFFECTS FUSING. 45 LOSS OF HEATER WIRES TO PRIME PRIMART OR A HEATER GROUP CHANNEL BACK UP WILL BE LOST. HONE. WITH EACH SUBSEQUENT FAILURE A LEVEL OF REDUNDANCY IS FUSES. 16 WEATER FUSE. WO EFFECT WILL LOST. WITH LOSS OF ALL PAINS ONE JOINT MAY MOVE AT A SLOWER BACK-UP BE WOTICED. THAN COMMANDED RATE IF A PRIOR FAILURE OF THE HEATER CHANNEL CAUSE(S): CIRCUIT HAS OCCURRED ARM DOES NOT RESPOND CORRECTLY TO FUSES. (1) WORST CASE COMMANDS. CREW WILL INHERENTLY COMPENSATE IN MANUAL AUGMENTED WIRING MECHANICAL HODE. SCHEMATIC 51140E316 BHOCK, VIBRATION, NO EFFECT ON CREW/VEHICLE OR CREW ACTION REVISION C. MATERIALS MISSION. CPRIME FUSES 24 THROUGH REDUMBANT PATHS APPLY BRAKES 37. D/U REMAINING FUSES 2 CREW TRAINING THROUGH 14 1 FUSE FOR AND 16) FAILED GROUP 2 fuses for CREW WILL BE TRAINED TO RECOGNIZE IF THE ARM IS RESPONDING ALTERNATE CORRECTLY TO COMMANDS. SYSTEM HEATER GROUP **HESSION CONSTRAINT** OPERATE UNDER VERNIER RATES WITHIN 10 FT. OF STRUCTURE.AUTO TRAJECTORIES MUST BE DESIGNED TO COME NO CLOSER THAN 5 FT. FROM STRUCTURE. THE OPERATOR MUST BE ABLE TO DETECT THAT THE ARM IS RESPONDING PROPERLY TO COMMANDS VIA WINDOW AND/OR CCTV VIEWS DURING ALL OPERATIONS, BOTH HEATER POWER BUSES TO BE IN AUTO WHEN OPERATING ARM. SCREEN FAILURES A: INDEPENDENT THERMOSTATS ARE NOT ACCESSIBLE, ARE NOT INSTRUMENTED AND THE REDUNDANT ELEMENTS ARE STILL OPERABLE. B: REDUNDANT ELEMENTS ARE STILL OPERABLE. OMRSD OFFLINE VERIFY INDIVIDUAL FUSES FOR WRIST AND END EFFECTOR WITH ARM SPLIT AT ELBOW. OMRSO ONLINE INSTALLATION NONE OMRSD ONE INE TURNAROUND

PREPARED BY: MFWG

SUPERCEDING DATE: 28 OC! 86

APPROVED BY: \_\_\_\_

RMS/MECH - 385